



Site Name	Feature Location	6 D's	Reasons	Existing species	Planting notes	Replant species
SEAGRAVE AVENUE	o/s 31	Stump	Stump only remaining 17/9/15, no further details known	Prunus padus	o/s 31 in verge in same location as felled tree	TR: Replanting: Prunus 'Sunset Boulevard'
SEAGRAVE AVENUE	o/s 38	Dangerous	Decay - Significant stem decay	Sorbus aria sp	between 38-40 in verge (same as felled tree)	TR: Replanting: Prunus 'Sunset Boulevard'
SEAGRAVE AVENUE	o/s 15	Stump	Stump only remaining 17/9/15, no further details known	Prunus sp	o/s 15 in verge (same location as felled tree)	TR: Replanting: Prunus 'Sunset Boulevard'
SEAGRAVE AVENUE	o/s 17-19	Dead	Dead	Prunus sp	Plant in verge o/s 17-19 (same as felled tree)	TR: Replanting, Prunus 'Sunset Boulevard'
SEAGRAVE AVENUE	o/s 18-20	Damaging	F/W damaged by shallow rooting, BT box cover displaced/damaged	Prunus sp	Plant in verge o/s 18-20 (same as felled tree)	TR: Replanting, Prunus 'Sunset Boulevard'
SEAGRAVE AVENUE	o/s 34-36	Stump	Stump only remaining 17/9/15, no further details known	Prunus padus	Plant in verge centrally o/s 34- 36 (same as felled tree)	TR: Replanting, Prunus 'Sunset Boulevard'